

HDHU.14SI and Maestro Information

HDHU.14SI

Draws less current than the factory head unit.

Needs no updates. Please don't try to update with 14+ software!
It doesn't end well. You will brick the unit.

MASETRO RR

- 1-Currently there is no firmware for the 2020 -2023 Harleys.
Gauges will not come up. The language on the ECM has changed. They are working on a fix
- 2-MRR will not work with any aftermarket tuners! The tuner will cause CAN crash and the radio will not connect. Also has been known to cause a current draw.
- 3-MRR can cause some bikes not to start after installation. This is also caused by a CAN crash. The fix is in the current Firmware. Just go into the menu for the MRR on the head unit and select **"Gauges on Demand"** that will remedy the problem.

Maestro is working on all of the above issues to give your customers a better experience.